



TYPE: Discus
TCDS - No.: 360

Page: 1 of 1

SCHEMPP - HIRTH
Flugzeugbau GmbH
Krebenstraße 25
D-73230 Kirchheim Germany
Tel. +49 7021 7298 - 0
Fax. +49 7021 7298 - 199



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1992-360/2	08.01.1993	Vertical elevator actuating rod inside the fin	-	ENG / GER
2.	1994-031	01.02.1994	Extension of the service time	-	ENG / GER
3.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
4.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
5.	2001-259	06.09.2001	Landing gear	ENG / GER	ENG / GER
6.	2003-048	06.03.2003	Horizontal stabilizer and elevator pushrod	-	ENG / GER
7.	2003-266	16.09.2003	In-flight failure of wing structure. A manufacturing defect cannot be ruled out at present. Due to the a.m. defect of airworthiness, the Luftfahrt-Bundesamt has legitimate doubts about the airworthiness of the aircraft and herewith declares the aircraft unairworthy.	-	-
8.	2003-266/2	02.10.2003	Failure of wing due to manufacturing defects	-	ENG / GER
9.	2003-280	02.10.2003	Elevator jamming due to separated balance weight	-	ENG / GER

