



**TYPE: DG – 600 M**  
**TCDS - No.: 866**

Page: 1 of 1

DG Flugzeugbau GmbH  
Otto Lilienthal Weg 2  
D-76646 Bruchsal  
Tel. +49 7251 3020-0  
Fax +49 7251 3020-200



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1992-367	22.10.1992	Emergency procedures! - Unintended pitch change into high pitch or feathering, excessive decrease in RPM or RPM-surfing	-	-
2.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
3.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
4.	2004-348	02.07.2004	Rudder – lower mounting of the rudder	-	ENG / GER
5.	2004-348/2	16.09.2004	Rudder – lower mounting of the rudder	-	ENG / GER

