



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1981-113	29.05.1981	Airbrake	-	-
2.	1981-112	03.06.1981	Ground connection between control stick and C.G. release	-	-
3.	1982-214	02.11.1982	Forward trim weight attachment bracket	-	-
4.	1983-118	14.06.1983	Landing gear, brake lever on Kobold hub pointing forward	-	-
5.	1983-158	12.09.1983	Air brakes, lower blade	-	-
6.	1993-083	15.03.1993	Inspection and replacement of trim weight holder	-	-
7.	1993-155	21.07.1993	Bonding of forward elevator mounting bracket in fuselage	-	-
8.	1993-157	09.08.1993	Landing gear drive	-	-
9.	1987-254/2	03.07.1997	Increase of service life	-	-
10.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
11.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
12.	1999-270	22.07.1999	Air brake locking in fuselage	-	ENG / GER
13.	2000-076	09.03.2000	Flight Controls - Jamming of the air brakes in extended position	-	ENG / GER
14.	2004-001	08.01.2004	Flight and Maintenance Manual – Update/Exchange of pages into the Flight and Maintenance Manual / Increase of structural life limit to max. 12000 flight hours	-	ENG / GER

