



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1991-110	18.04.1991	Pedal adjustment cable	-	-
2.	1991-172	23.10.1991	Deflector at fuselage aileron automatic connectors	-	-
3.	1993-001/3	09.04.1998	L'Hottellier ball and socket connectors with lock plates	ENG / GER	-
4.	1994-001/2	09.04.1998	L'Hottellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
5.	1999-267	06.07.1999	Obstruction of emergency canopy jettison	-	ENG / GER
6.	2000-083	09.03.2000	Flight Controls - Jamming of the air brakes in extended position	-	ENG / GER
7.	1999-267/2	15.03.2001	Obstruction of emergency canopy jettison and avoidance of possible injuries	-	ENG / GER
8.	2002-043	21.02.2002	Extension of service time	-	ENG / GER

