



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	1999-268	06.07.1999	Obstruction of emergency canopy jettison	-	ENG / GER
4.	2000-067	09.03.2000	Flight and Maintenance Manual	-	ENG / GER
5.	2000-084	09.03.2000	Flight Controls - Jamming of the air brakes in extended position	-	ENG / GER
6.	2000-086	23.03.2000	Wings, water-tanks, drain tube of outer tank in wing leading edge	-	ENG / GER
7.	1999-268/2	15.03.2001	Obstruction of emergency canopy jettison and avoidance of possible injuries	-	ENG / GER
8.	2001-200	26.07.2001	Extension of service time	-	ENG / GER
9.	2002-082	04.04.2002	Exchange of pages into the Flight- and Maintenance Manual - various items updated (tow hook, annual inspection) - optional trim by removal of tail fin battery	-	ENG / GER

