



TYPE: Stemme S-10
TCDS - No.: 846

Page: 1 of 2

STEMME AG
Flugplatzstraße F2, Nr. 7
15344 Strausberg
Deutschland
Tel. +49 3341 3612-0
Fax. +49 3341 3612-30



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	1993-001/3	09.04.1998	L'Hotellier ball and socket connectors with lock plates	ENG / GER	-
2.	1994-001/2	09.04.1998	L'Hotellier ball and socket connectors with locking cams (type 45 ratchet)	ENG / GER	-
3.	1998-323	01.07.1998	Flight Controls - Cracking in the elevator control coupling	-	ENG / GER
4.	1998-324	30.07.1998	Flight Controls - Replacement of the flap drive rocker P/N 10SW-RMW	-	ENG / GER
5.	1998-323/2	08.10.1998	Flight Controls - Cracking in the elevator control coupling	-	ENG / GER
6.	1998-400	22.10.1998	ROTAX 914 F2/S1 Engine Controls - Redesign of Wastegate Control and exchange of oil tubes	-	ENG / GER
7.	1999-224	04.06.1999	Variable pitch propeller - Propeller fork of propellers 10AP-V and 11AP-V	-	ENG / GER
8.	1999-224/2	05.08.1999	Variable pitch propeller - Propeller fork of propellers 10AP-V and 11AP-V	-	ENG / GER
9.	1999-224/3	08.09.1999	Variable pitch propeller - Propeller fork of propellers 10AP-V and 11AP-V	-	ENG / GER
10.	1999-224/4	10.12.1999	Variable pitch propeller - Propeller fork of propellers 10AP-V and 11AP-V	-	ENG / GER
11.	2000-369	30.11.2000	Air brake eye bolts and air brake sheets and Landing gear door hinges and door actuation	-	ENG / GER
12.	1999-224/5	22.03.2001	Variable pitch propeller - Propeller fork of propellers 10AP-V and 11AP-V	-	ENG / GER
13.	2002-113	02.05.2002	MAN drive shafts, one time inspection of the metal flanges on both ends of the drive shaft	-	ENG / GER
14.	2002-156	13.06.2002	Fire protection - preventive actions for enhanced fire protection	ENG / GER	ENG / GER
15.	2002-389	25.11.2002	Gear Box 11AG; possible rupture of the lower cog wheel in the gear box P/N 11AG	-	ENG / GER
16.	2002-389/2	17.04.2003	Gear Box 11AG; possible rupture of the lower cog wheel in the gear box P/N 11AG Replacement of the lower cog wheel by a modified cog wheel	-	ENG / GER





TYPE: Stemme S-10
TCDS - No.: 846

Page: 2 of 2

STEMME AG
Flugplatzstraße F2, Nr. 7
15344 Strausberg
Deutschland
Tel. +49 3341 3612-0
Fax. +49 3341 3612-30



No.	AD Number	Effective Date	Subject	AD Supplement	Service Bulletin
1.	2004-443	27.09.2004	Flight Controls - Aileron control system / loose bearings	-	ENG / GER
2.	2005-228	24.06.2005	Pressure lines between airbox and carburetors and differential fuel pressure sensor	-	ENG / GER
3.	2006-197	17.07.2006	Exhaust-System – Inspection of Exhaust-System for Cracks	-	ENG / GER

